


WIRING THE *RCS PROFESSIONAL* PRO-3 ESC w/Track and/or Battery power. How to wire incandescent & LED lighting.

N.B. Maximum current on each transistor is 100 ma. See page # 3.

Plug in pushbutton used for:
Speed Calibration & Programming.

The ● symbol indicates
where wires are joined.



WIRING THE *RCS PROFESSIONAL* PRO-3 ESC w/Track and/or Battery power. How to wire incandescent & LED lighting.

N.B. Maximum current on each transistor is 100 ma. See page # 3.

